

UNITED STATES OF AMERICA
DEPARTMENT OF TRANSPORTATION
FEDERAL AVIATION ADMINISTRATION

Air Agency Certificate

Number YB5R630Y

This certificate is issued to

Byron Products, Inc.

whose business address is

**3781 Port Union Road
Fairfield, Ohio 45014**

*upon finding that its organization complies in all respects
with the requirements of the Federal Aviation Regulations
relating to the establishment of an Air Agency, and is
empowered to operate an approved* **Repair Station**

with the following ratings:


Limited - Specialized Services

*This certificate, unless canceled, suspended, or revoked,
shall continue in effect* **Indefinitely.**

Date issued:

Reissued: February 29, 2008

Issued: April 12, 2000

By direction of the Administrator


Debra Z. Joiner - Manager

CVG FSDO, Cincinnati, Ohio

**This Certificate is not Transferable, AND ANY MAJOR CHANGE IN THE BASIC FACILITIES, OR IN THE LOCATION THEREOF,
SHALL BE IMMEDIATELY REPORTED TO THE APPROPRIATE REGIONAL OFFICE OF THE FEDERAL AVIATION ADMINISTRATION**

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both

A003 . Ratings and Limitations

HQ Control: 01/30/2004

HQ Revision: 010

The Certificate Holder is authorized the following Ratings and/or Limitations:

Class Ratings

None Authorized

Limited Ratings

Rating

Manufacturer

Make/Model

Limitations

None Authorized

Limited Ratings - Specialized Services

Rating

Specifications

Limitations

Heat
Treating

MIL-H-6875 as revised

Repair limitations as contained in the referenced
Civil or Military Specification.

Welding

AMS STD 1595, AMS STD 2219, AMS 2685,
MIL-H-6875, as revised.

Repair limitations as contained in the referenced
Civil or Military Specification.

Brazing

AMS 2675, AMS 2662, AMS 2670, AMS 2671,
MIL-B-7883, as revised

Repair limitations as contained in the referenced
Civil or Military Specification.

Thermal
Spray

In accordance with FAA approved
manufacturer's or military specifications.

Repair limitations as contained in the referenced
Civil or Military Specification.